

June 25, 2003

State of Utah  
Department of Natural Resources  
Division of Oil, Gas and Mining  
Attn: Mr. Paul B. Baker  
Senior Reclamation Biologist  
1594 West North Temple, Suite 1210  
PO Box 145801  
Salt Lake City, UT 84114-5801

\* m/047/032  
m/047/022  
Please  
file.

Dear Mr. Baker:

This letter is in response to your letter of June 9, 2003. As we discussed in our phone conversation we could best address your questions by revising our map to include and correct ambiguities and missing data. Please find attached the revised map. I have highlighted the specific changes we made to address your questions below;

- 1.) We have removed the cross-hatching in the reclaimed area and highlighted the still disturbed area of the road. Please note the cross-hatching in the Uintah County disturbed area in section 30 is light.
- 2.) We cross hatched the pond to indicate it is part of the disturbed area and recalculated all the areas within the map. Each of these areas is highlighted in the legend.
- 3.) We made the cross-hatching within the Crown Extraction Facility the same. Again we recalculated all the individual areas within the map.
- 4.) We removed the title of Crown Asphalt Lease in the flare stack area of the map and accurately labeled it Crown Extraction Facility. You will note that the numbers have changed (increased) from the last map. This is due to the fact that the undisturbed area within this section of the map was not included in the original number. The number only included the highlighted flare stack. At our meeting we agreed to include all the leased area within the Crown Extraction Facility. This change increased the disturbed area of the Crown Extraction Facility by 3.75 acres.

As part of the effort to address your questions we have cleaned up the map by removing the double lines and recalculated each individual area within the map. This resulted in some minor changes between several areas within the map. Below is a table highlighting the resulting changes.

RECEIVED  
JUN 26 2003  
DIV. OF OIL, GAS & MINING

MAP AREA	ORIGINAL	REVISED	DIFF.	COMMENT
Crown Extraction Facility Site	21.11	24.86	3.75	Added the undisturbed area within the leased area.
Crown Disturbed Area in Section 31	26.53	26.53	0	
Crown Collection Pond Section 31	0.35	0.40	0.05	Due to removal of multiple lines & Recalculating the area.
Uintah County Area (Lease)	17.58	17.58	0	
Uintah County Disturbed Area in Section 30	46.27	48.32	2.05	Added road to mine.
Uintah County Collection Pond section 30	0.28	0.34	0.06	Due to removal of multiple lines & Recalculating the area.
Crown Reclaimed Area in Section 31	0.41	0.65	0.24	Due to removal of multiple lines & Recalculating the area.
Uintah County Reclaimed Area in section 30	10.17	9.48	(0.69)	Removed mine road and removed multiple lines.
<b>TOTAL</b>	122.7	128.16	5.46	

The results of these changes is that the total reclaimed area for Crown is 0.65 areas and for Uintah County 9.48 areas. The total disturbed areas for Crown is 51.79 and for Uintah County 66.24.

I hope these changes have addressed all your questions but if you need any clarification or have other questions, please call me at (586) 268-3175.

Sincerely,

*William E. Kraemer*

William E. Kraemer